CORNER RECORD	Document Number	3529 - 34 - 79
City of ManmoTh Lakes	County ofMGn	© California
Brief Legal Description Lot 48 MB4, P	6 18. , Mammoth	Slopes No.1
CORNER TYP Government Corner Meander Rancho Date of Survey	Control Property Other	COORDINATES (Optional) N E Zone Datum Elev
Corner — Left as found Found and tagged] Established [] Re	established 🛛 Rebuilt 🗌
Fad 1/2" Rebor & Cop @ The Hily Fad RR Spk 0.4' below paver Used these points 70 proportion A description of the physical condition of the monument as SeT 7/8" Rebor's & Cops 6.5 4587	s found and as set or reset:	FOIEST Frail.
SURVEYOR'S STATEMENT This Corner Record was prepared by me or under my direction.	rection in conformance wi	1
Signed L.S. or R.C.E. N	1997. Jumber 4587	SEAL
This Corner Record was received	19 9 and examine 19 9 and examine SURY EYOR EXP. 9-30-95	No. 4686

